



American Hakko Products, Inc.

# PRODUCT BULLETIN

**Bulletin No:** PB444  
**Issue Date:** 12-10-2019  
**Effective Date:** 12-10-2019

**Description/Title:**  
Discontinuation of the HAKKO FR-1418 SMD Rework System

**Part No:**  
FR1418-xx

**Specification:**  
**DISCONTINUED**

**Comments:**  
The HAKKO FR-1418 SMD Rework System has been discontinued effective immediately.

The discontinued system will be replaced by the NEW HAKKO HJ4000-SET SMD Rework System. Please reference Product Bulletin PB445.

For more information, please visit [www.HakkoUSA.com](http://www.HakkoUSA.com), e-mail [Support@HakkoUSA.com](mailto:Support@HakkoUSA.com), or call 1-800-88-HAKKO (42556).

