



American Hakko Products, Inc.

PRODUCT BULLETIN

Bulletin No: PB446
Issue Date: 4-13-2020
Effective Date: 4-13-2020

Description/Title:
Discontinuation of 999-224B Boom Stand

Part No:
999-224B

Specification:
DISCONTINUED



Comments:
The HAKKO 999-224B Boom Stand will be discontinued effective 4-13-2020 or once remaining supply has been exhausted.

For users with newer HAKKO FR-810, FR-810B, and FR-811 SMD Hot Air Rework Stations, the HAKKO C1392B and C5028 Rework Fixtures are compatible alternatives. Note that the C1392B will require the B5059 Handpiece Fixture Adapter.

For users with older HAKKO Hot Air SMD Rework Stations not listed above, the HAKKO C1392B is the compatible alternative.

For more information, please visit www.HakkoUSA.com, e-mail Support@HakkoUSA.com, or call 1-800-88-HAKKO (42556).